

DAFTAR ISI

HALAMAN JUDUL	Error! Bookmark not defined.
LEMBAR PERSETUJUAN	Error! Bookmark not defined.
LEMBAR PENGESAHAN	Error! Bookmark not defined.
LEMBAR PERNYATAAN	Error! Bookmark not defined.
KATA PENGANTAR.....	Error! Bookmark not defined.
ABSTRAK	Error! Bookmark not defined.
<i>ABSTRACT</i>	Error! Bookmark not defined.
DAFTAR ISI.....	i
DAFTAR TABEL	iv
DAFTAR GAMBAR	vi
DAFTAR RUMUS.....	vii
DAFTAR LAMPIRAN	8
BAB I PENDAHULUAN.....	Error! Bookmark not defined.
1.1 Latar Belakang	Error! Bookmark not defined.
1.2 Rumusan Masalah	Error! Bookmark not defined.
1.3 Tujuan Penelitian.....	Error! Bookmark not defined.
1.4 Manfaat Penelitian	Error! Bookmark not defined.
1.5 Batasan Masalah.....	Error! Bookmark not defined.
BAB II TINJAUAN PUSTAKA	Error! Bookmark not defined.
2.1 Produktivitas	Error! Bookmark not defined.
2.1.1 Jenis-Jenis Produktivitas	Error! Bookmark not defined.
2.1.2 Sistem Produktivitas	Error! Bookmark not defined.
2.1.3 Efektivitas	Error! Bookmark not defined.
2.1.4 Aspek-aspek Efektivitas.....	Error! Bookmark not defined.

2.1.5	<i>Overall Equipment Effectiveness (OEE)</i>	Error! Bookmark not defined.
2.2	Metode DMAIC	Error! Bookmark not defined.
2.3	Metode <i>Failure Mode Effect Analysis</i> (FMEA)	Error! Bookmark not defined.
2.3.1	Tipe dan Tujuan Implementasi Metode FMEA	Error! Bookmark not defined.
2.3.2	Variabel Pada Metode FMEA	Error! Bookmark not defined.
2.4	Kerangka Pemikiran.....	Error! Bookmark not defined.
2.5	Penelitian Terkait.....	Error! Bookmark not defined.
BAB III METODE PENELITIAN		Error! Bookmark not defined.
3.1	Objek Penelitian	Error! Bookmark not defined.
3.2	Alur Penelitian	Error! Bookmark not defined.
3.3	Jenis Data dan Sumber Data	Error! Bookmark not defined.
3.3.1	Data Primer	Error! Bookmark not defined.
3.3.2	Data Sekunder	Error! Bookmark not defined.
3.4	Jenis Penelitian.....	Error! Bookmark not defined.
3.5	Metode Pengumpulan Data.....	Error! Bookmark not defined.
3.6	Teknik Pengolahan Data	Error! Bookmark not defined.
3.6.1	Pengolahan Data Pencapaian OEE.	Error! Bookmark not defined.
3.6.2	Pengolahan Data Metode DMAIC dan FMEA	Error! Bookmark not defined.
BAB IV HASIL DAN PEMBAHASAN.....		Error! Bookmark not defined.
4.1	Profil Perusahaan	Error! Bookmark not defined.
4.2	Analisis DMAIC	Error! Bookmark not defined.
4.2.1	<i>Define Phase</i>	Error! Bookmark not defined.
4.2.2	<i>Measure Phase</i>	Error! Bookmark not defined.

4.2.3	<i>Analyze Phase</i>	Error! Bookmark not defined.
4.3	Analisis FMEA	Error! Bookmark not defined.
4.3.1	Analisis <i>Severity</i>	Error! Bookmark not defined.



4.3.2	Analisis <i>Occurence</i>	Error! Bookmark not defined.
4.3.3	Analisis <i>Detection</i>	Error! Bookmark not defined.
4.3.4	Hasil Perhitungan <i>Risk Priority Number</i> (RPN)	Error! Bookmark not defined.
4.4	<i>Improvement Phase</i>	Error! Bookmark not defined.
4.5	<i>Control Phase</i>	Error! Bookmark not defined.
4.5.1	Perhitungan RPN Pasca Mitigasi ...	Error! Bookmark not defined.
4.5.2	Korelasi RPN Pasca Mitigasi Dengan OEE	Error! Bookmark not defined.
BAB V KESIMPULAN DAN SARAN		Error! Bookmark not defined.
5.1	Kesimpulan	Error! Bookmark not defined.
5.2	Saran.....	Error! Bookmark not defined.
DAFTAR PUSTAKA		Error! Bookmark not defined.
LAMPIRAN		Error! Bookmark not defined.
RIWAYAT PENULIS		Error! Bookmark not defined.

DAFTAR TABEL

Tabel 1. 1 Perhitungan <i>Availability</i> Pada Mesin <i>Notching & Drying</i>	Error! Bookmark not defined.
Tabel 1. 2 Perhitungan <i>Performance</i> Pada Mesin <i>Notching & Drying</i>	Error! Bookmark not defined.
Tabel 1. 3 Perhitungan <i>Quality</i> Pada Proses <i>Notching and Drying</i> Periode Mei 2024 – Maret 2025	Error! Bookmark not defined.
Tabel 1. 4 OEE Pada Proses <i>Notching and Drying</i> Periode Mei 2024 Hingga Maret 2025	Error! Bookmark not defined.
Tabel 1. 5 Justifikasi 8 Mesin Dari 16 Mesin <i>Notching and Drying</i>	Error! Bookmark not defined.
Tabel 2. 1 Standar OEE	Error! Bookmark not defined.
Tabel 2. 2 FMEA <i>Breakdown</i>	Error! Bookmark not defined.
Tabel 2. 3 Kriteria Penilaian <i>Severity</i>	Error! Bookmark not defined.
Tabel 2. 4 Kriteria Penilaian <i>Occurance</i>	Error! Bookmark not defined.
Tabel 2. 5 Kriteria Penilaian <i>Detection</i>	Error! Bookmark not defined.
Tabel 2. 6 Penelitian Terkait.....	Error! Bookmark not defined.
Tabel 3. 1 <i>Failure Equipment Problem List</i>	Error! Bookmark not defined.
Tabel 3. 2 FMEA <i>Breakdown</i>	Error! Bookmark not defined.
Tabel 4. 1 Data <i>Downtime</i> Periode Mei 2024 – Maret 2025	Error! Bookmark not defined.
Tabel 4. 2 Skala Penilaian <i>Severity</i>	Error! Bookmark not defined.
Tabel 4. 3 Nilai <i>Severity</i> Proses <i>Notching dan Drying</i>	Error! Bookmark not defined.
Tabel 4. 4 Skala Penilaian <i>Occurance</i>	Error! Bookmark not defined.
Tabel 4. 5 Nilai <i>Occurence</i> Proses <i>Notching dan Drying</i>	Error! Bookmark not defined.
Tabel 4. 6 Skala Penilaian <i>Detection</i>	Error! Bookmark not defined.
Tabel 4. 7 Nilai <i>Detection</i> Proses <i>Notching dan Drying</i>	Error! Bookmark not defined.
Tabel 4. 8 Perhitungan RPN pada Proses <i>Notching dan Drying</i>	Error! Bookmark not defined.

Tabel 4. 9 Usulan Perbaikan Untuk Mencegah Terjadinya Elektroda Putus . **Error! Bookmark not defined.**

Tabel 4. 10 Tabel Usulan Perbaikan Pembuata SOP**Error! Bookmark not defined.**

Tabel 4. 11 Faktor Penyebab Perubahan Posisi Pada *Air Blow Mold* **Error! Bookmark not defined.**


Tabel 4. 12 *Check Sheet Daily* Pengecekan *Air Blow***Error! Bookmark not defined.**

Tabel 4. 13 *Loss Time Production Down* Sebelum Mitigasi**Error! Bookmark not defined.**

Tabel 4. 14 *Loss Time Production Down* Setelah Mitigasi**Error! Bookmark not defined.**

Tabel 4. 15 Hasil Kuesioner FMEA Sebelum Dilakukan Mitigasi **Error! Bookmark not defined.**

Tabel 4. 16 Hasil Kuesioner FMEA Pasca Mitigasi**Error! Bookmark not defined.**



Tabel 4. 17 Perhitungan Nilai *Availability* Pasca Mitigasi **Error! Bookmark not defined.**

Tabel 4. 18 Tabel Nilai *Availability* Sebelum Mitigasi **Error! Bookmark not defined.**

Tabel 4. 19 Nilai *Performance* Pasca Mitigasi.....**Error! Bookmark not defined.**


Tabel 4. 20 Nilai *Quality* Pasca Mitigasi**Error! Bookmark not defined.**

Tabel 4. 21 Nilai OEE Sebelum Dilakukan Mitigasi *Risk Priority Number* (RPN)

.....**Error! Bookmark not defined.**

Tabel 4. 22 Nilai OEE Pasca Dilakukan Mitigasi *Risk Priority Number* (RPN)

.....**Error! Bookmark not defined.**



DAFTAR GAMBAR

Gambar 1. 1 Material Sebelum Proses *Notching & Drying***Error! Bookmark not defined.**

Gambar 1. 2 Material Setelah proses *Notching & Drying***Error! Bookmark not defined.**

Gambar 1. 3 *Overall Equipment Effectiveness* Proses *Notching & Drying*... **Error! Bookmark not defined.**

Gambar 2. 1 Skema Sistem Produktivitas.....**Error! Bookmark not defined.**

Gambar 2. 2 Langkah Analisis Metode DMAIC ...**Error! Bookmark not defined.**

Gambar 2. 3 Kerangka Pemikiran.....**Error! Bookmark not defined.**

Gambar 3. 1 *Flowchart* Alur Penelitian**Error! Bookmark not defined.**

Gambar 3. 2 *OEE Achievement Vs World Class Target***Error! Bookmark not defined.**

Gambar 3. 3 *OEE Factor Achievement Vs World Class Target***Error! Bookmark not defined.**

Gambar 3. 4 *Long Time Breakdown Machines Pareto Diagram***Error! Bookmark not defined.**

Gambar 4. 1 Alur Proses *Notching and Drying***Error! Bookmark not defined.**

Gambar 4. 2 Diagram *Fishbone***Error! Bookmark not defined.**

Gambar 4. 3 *Stopper* Untuk Menahan Elektroda di Bagian *Loader* **Error! Bookmark not defined.**

Gambar 4. 4 *Splicing Table* Untuk Penyambungan Elektroda Putus **Error! Bookmark not defined.**


Gambar 4. 5 *Manual Splicing Table* Untuk Penyambungan Elektroda **Error! Bookmark not defined.**

Gambar 4. 6 Data *Scrap* Pada Proses *Notching and Drying***Error! Bookmark not defined.**

Gambar 4. 7 Penambahan NG *Tag Scrap* Area Elektroda**Error! Bookmark not defined.**

DAFTAR RUMUS

- (1. 1)..... **Error! Bookmark not defined.**
(2. 1)..... **Error! Bookmark not defined.**
(2. 2)..... **Error! Bookmark not defined.**
(2. 3)..... **Error! Bookmark not defined.**
(2. 4)..... **Error! Bookmark not defined.**
(2. 5)..... **Error! Bookmark not defined.**
(3. 1)..... **Error! Bookmark not defined.**
(3. 2)..... **Error! Bookmark not defined.**
(3. 3)..... **Error! Bookmark not defined.**
(3. 4)..... **Error! Bookmark not defined.**



DAFTAR LAMPIRAN

Lampiran 1 Lembar Bimbingan Proposal Tugas Akhir **Error! Bookmark not defined.**

Lampiran 2 Lembar Bimbingan Proposal Tugas Akhir (lanjutan)..... **Error! Bookmark not defined.**

Lampiran 3 Lembar Bimbingan Tugas Akhir**Error! Bookmark not defined.**

Lampiran 4 Dokumentasi Sidang Tugas Akhir**Error! Bookmark not defined.**

