

DAFTAR ISI

COVER	Error! Bookmark not defined.
LEMBAR PERSETUJUAN	Error! Bookmark not defined.
LEMBAR PENGESAHAN	Error! Bookmark not defined.
LEMBAR PERNYATAAN	Error! Bookmark not defined.
KATA PENGANTAR.....	Error! Bookmark not defined.
ABSTRAK	Error! Bookmark not defined.
DAFTAR ISI.....	1
DAFTAR TABEL	4
DAFTAR GAMBAR.....	5
DAFTAR LAMPIRAN.....	7
BAB I PENDAHULUAN.....	Error! Bookmark not defined.
1. 1 Latar Belakang	Error! Bookmark not defined.
1. 2 Rumusan Masalah	Error! Bookmark not defined.
1. 3 Tujuan Penelitian.....	Error! Bookmark not defined.
1. 4 Manfaat Penelitian.....	Error! Bookmark not defined.
1. 5 Batasan Masalah.....	Error! Bookmark not defined.
1. 6 Asumsi Penelitian.....	Error! Bookmark not defined.
BAB II TINJAUAN PUSTAKA.....	Error! Bookmark not defined.
2. 1 Proses Produksi	Error! Bookmark not defined.
2.1.1 Pengertian Proses Produksi.....	Error! Bookmark not defined.
2.1.2 Fungsi Produksi.....	Error! Bookmark not defined.
2.1.3 Jenis – jenis Proses Produksi	Error! Bookmark not defined.
2. 2 Proses Pemesinan (<i>Machining Proses</i>).....	Error! Bookmark not defined.
2.2.1 Pengertian Proses Pemesinan (<i>Machining Process</i>)	Error! Bookmark not defined.
2.2.2 Mesin <i>CNC Milling</i>	Error! Bookmark not defined.
2. 3 Kualitas Produk.....	Error! Bookmark not defined.
2.3.1 Pengertian Kualitas	Error! Bookmark not defined.
2.3.2 Dimensi – Dimensi Kualitas	Error! Bookmark not defined.
2.3.3 Faktor – Faktor yang Mempengaruhi Kualitas	Error! Bookmark not defined.
2.3.4 Pentingnya Kualitas	Error! Bookmark not defined.

2. 4 Pengendalian Kualitas	Error! Bookmark not defined.
2.4.1 Peta Kendali (<i>Control Chart</i>).....	Error! Bookmark not defined.
2.4.2 Diagram Pareto (<i>Pareto Chart</i>).....	Error! Bookmark not defined.
2.4.3 Diagram Sebab – Akibat (<i>Cause and Effect Diagram / Fishbone Diagram</i>).....	20
2. 5 Jig and Fixture	21
2. 6 Proses Pencekaman (<i>Clamping</i>)	Error! Bookmark not defined.
2. 7 Design For Manufacturing (<i>DFM</i>)	28
2. 8 Define, Measure, Analyze, Improve, and Control (<i>DMAIC</i>)	29
2. 9 Penelitian Terkait	31
BAB III METODOLOGI	34
3. 1 Objek Penelitian	34
3. 2 Prosedur Penelitian.....	34
3. 3 Data dan Informasi	36
3.3.1 Data Primer	36
3.3.2 Data Sekunder	36
3. 4 Teknik Pengumpulan Data	36
3. 5 Analisis Data	37
3. 6 Perbaikan.....	37
BAB IV HASIL DAN PEMBAHASAN	38
4.1 Gambaran Umum Perusahaan	38
4.2 Pengumpulan Data	39
4.2.1 Alur Proses Produksi <i>Part Cover Oil Pump</i>	39
4.2.2 Data Cacat Produk <i>Cover Oil Pump</i>	39
4.2.3 Cacat <i>Flatness</i> (Kerataan).....	41
4.3 Analisis Data	44
4.3.1 Mesin 1 (Tekanan <i>Clamping</i> Terlalu Besar).....	45
4.3.2 Mesin 2 (Tidak Ada Datum <i>Fix</i> Pada <i>Clamping</i>)	45
4.3.3 Mesin 3 (Radius <i>Clamping</i> Terlalu Kecil)	Error! Bookmark not defined.
4.3.4 Solusi Permasalahan.....	46
4.3.5 Desain <i>Clamping</i> Awal	47
4.4 Perbaikan.....	47
4.4.1 Perbaikan Tekanan <i>Clamping</i>	48

4.4.2	Perbaikan Desain <i>Clamping</i>	48
4.5	Konsep Desain <i>Clamping</i>	48
4.5.1	Customer Needs	48
4.5.2	Menentukan Target <i>Specifications</i>	49
4.5.3	Matriks Customer Needs dan Target <i>Specifications</i>	50
4.5.4	<i>Clamping</i> Desain	51
4.5.5	Prototype Desain <i>Clamping</i>	54
4.6	Hasil Perbaikan	55
4.6.1	Proses Pencekaman <i>Clamping</i> Baru	55
4.6.2	Kontrol Hasil Proses <i>Flatness</i>	56
4.6.3	<i>Lifetime</i> / Umur <i>Clamping</i>	59
4.6.4	Penurunan Jumlah Cacat <i>Flatness</i>	61
BAB V KESIMPULAN DAN SARAN		63
5.1	Kesimpulan	63
5.2	Saran	64
DAFTAR PUSTAKA		65
LAMPIRAN		68
RIWAYAT PENULIS		78



DAFTAR TABEL

Tabel 2. 1 <i>Minimum values for process capability</i>	Error! Bookmark not defined.
Tabel 2. 2 Tabel Penelitian Terkait	31
Tabel 4. 1 Hasil Pengukuran Flatness COP	Error! Bookmark not defined.
Tabel 4. 2 Hasil Pengukuran <i>Flatness COP</i>	Error! Bookmark not defined.
Tabel 4. 3 <i>Customer Needs</i>	Error! Bookmark not defined.
Tabel 4. 4 <i>Target Specification</i>	Error! Bookmark not defined.
Tabel 4. 5 Matriks <i>Customer Needs</i> dan <i>Target Specifications</i>	Error! Bookmark not defined.
Tabel 4. 6 Spesifikasi <i>Clamping</i> Baru.....	Error! Bookmark not defined.
Tabel 4. 7 Hasil Pengukuran <i>Flatness CMM</i>	Error! Bookmark not defined.
Tabel 4. 8 Perbandingan Hasil Perbaikan Desain <i>Clamping</i>	Error! Bookmark not defined.
Tabel 4. 9 Perbandingan Jumlah Cacat <i>Flatness</i> ...	Error! Bookmark not defined.
Tabel 4. 10 Tabel Perbandingan <i>Analysis Cost</i>	Error! Bookmark not defined.

KARAWANG

DAFTAR GAMBAR

Gambar 1. 1 Grafik Cacat Produk PT SAS (Rata-rata 3 Bulan)	Error! Bookmark not defined.
Gambar 1. 2 Dimensi <i>Flatness</i> COP	Error! Bookmark not defined.
Gambar 2. 1 Contoh Peta X dan R.....	Error! Bookmark not defined.
Gambar 2. 2 <i>Natural tolerance limits and process</i>	Error! Bookmark not defined.
Gambar 2. 3 Contoh Diagram <i>Pareto</i>	Error! Bookmark not defined.
Gambar 2. 4 Contoh Diagram Sebab Akibat	Error! Bookmark not defined.
Gambar 2. 5 <i>Template Jigs</i>	Error! Bookmark not defined.
Gambar 2. 6 <i>Plate jigs</i>	Error! Bookmark not defined.
Gambar 2. 7 <i>Sandwich jigs</i>	Error! Bookmark not defined.
Gambar 2. 8 <i>Angle plate jigs</i>	Error! Bookmark not defined.
Gambar 2. 9 <i>Box jigs</i>	Error! Bookmark not defined.
Gambar 2. 10 <i>Channel jigs</i>	Error! Bookmark not defined.
Gambar 2. 11 <i>Leaf jigs</i>	Error! Bookmark not defined.
Gambar 2. 12 <i>Indexing jigs</i>	Error! Bookmark not defined.
Gambar 2. 13 <i>Trunnion jigs</i>	Error! Bookmark not defined.
Gambar 2. 14 <i>Pump jigs</i>	Error! Bookmark not defined.
Gambar 2. 15 <i>Multistation jigs</i>	Error! Bookmark not defined.
Gambar 2. 16 Gambar macam macam klem.....	Error! Bookmark not defined.
Gambar 2. 17 Blok Siku dan Kelengkapanya	Error! Bookmark not defined.
Gambar 2. 18 Blok <i>Vee</i> dan Kelengkapanya	Error! Bookmark not defined.
Gambar 2. 19 <i>Design For Manufacture</i>	Error! Bookmark not defined.
Gambar 2. 20 <i>Design for manufacturing flow</i>	Error! Bookmark not defined.
Gambar 2. 21 Siklus DMAIC.....	Error! Bookmark not defined.
Gambar 3. 1 <i>Flowchart</i> Prosedur Penelitian	Error! Bookmark not defined.
Gambar 4. 1 Logo PT Sinar Alum Sarana	Error! Bookmark not defined.

Gambar 4. 2 Alur Proses Produksi *Part Cover Oil Pump***Error! Bookmark not defined.**

Gambar 4. 3 Grafik Cacat Produk PT SAS (Data 3 bulan)**Error! Bookmark not defined.**

Gambar 4. 4 Diagram *Pareto* Cacat Produk *COP* .**Error! Bookmark not defined.**

Gambar 4. 5 Standar Dimensi *Flatness COP***Error! Bookmark not defined.**

Gambar 4. 6 Pengecekan *Flatness by Feeler***Error! Bookmark not defined.**

Gambar 4. 7 Proses Pengukuran *Flatness COP by CMM***Error! Bookmark not defined.**

Gambar 4. 8 Sebaran Data *Flatness COP***Error! Bookmark not defined.**

Gambar 4. 9 Fishbone Diagram Analysis**Error! Bookmark not defined.**

Gambar 4. 10 Proses Pencekaman *Part Cover Oil Pump***Error! Bookmark not defined.**

Gambar 4. 11 Bekas Pencekaman Pada *Clamping* **Error! Bookmark not defined.**

Gambar 4. 12 Proses Pencekaman *Clamping* Bengkok**Error! Bookmark not defined.**

Gambar 4. 13 Radius *Clamping***Error! Bookmark not defined.**

Gambar 4. 14 Desain *Clamping Type A* (Sebelum Perbaikan)**Error! Bookmark not defined.**

Gambar 4. 15 Desain *Clamping Type B* (Sebelum Perbaikan)**Error! Bookmark not defined.**

Gambar 4. 16 *Design For Manufacture Flow***Error! Bookmark not defined.**

Gambar 4. 17 Konsep Desain *Clamping Type A* (Tampak Samping) **Error! Bookmark not defined.**

Gambar 4. 18 Konsep Desain *Clamping Type A* (Tampak Atas) **Error! Bookmark not defined.**

Gambar 4. 19 Konsep Desain *Clamping Type B* (Tampak Samping) **Error! Bookmark not defined.**

Gambar 4. 20 Konsep Desain *Clamping Type B* (Tampak Atas)**Error! Bookmark not defined.**

Gambar 4. 21 Konsep Desain Radius *Clamping Type A***Error! Bookmark not defined.**

Gambar 4. 22 Konsep Desain Radius *Clamping Type B* Error! Bookmark not defined.

Gambar 4. 23 *Prototype Clamping Type A*.....Error! Bookmark not defined.

Gambar 4. 24 *Prototype Clamping Type B*.....Error! Bookmark not defined.

Gambar 4. 25 *Clamping* dengan Datum *Fix*Error! Bookmark not defined.

Gambar 4. 26 *Clamping* dengan Radius 5 mmError! Bookmark not defined.

Gambar 4. 27 Proses Pencekaman *Part*Error! Bookmark not defined.

Gambar 4. 28 Hasil Cek Dimensi *Flatness After* Perbaikan Error! Bookmark not defined.

Gambar 4. 29 Peta Kendali X *Flatness*Error! Bookmark not defined.

Gambar 4. 30 Peta Kendali R *Flatness*Error! Bookmark not defined.

Gambar 4. 31 Grafik Persentase Cacat *Flatness*...Error! Bookmark not defined.

Gambar 4. 32 Grafik Cacat Produk *Cover Oil Pump* Error! Bookmark not defined.



DAFTAR LAMPIRAN

Lampiran 1.a Form Bimbingan Seminar Proposal. Error! Bookmark not defined.

Lampiran 1.b Form Bimbingan Seminar Proposal Error! Bookmark not defined.

Lampiran 2 Form Bimbingan Tugas Akhir.....Error! Bookmark not defined.

Lampiran 3 *Drawing Clamping Type A*Error! Bookmark not defined.

Lampiran 4 *Drawing Clamping Type B*Error! Bookmark not defined.

Lampiran 5 Monitoring Cacat Produk COP Bulan Agustus Error! Bookmark not defined.

Lampiran 6 Monitoring Cacat Produk COP Bulan September Error! Bookmark not defined.

Lampiran 7 *Form Minute Meeting Production Engineering***Error! Bookmark not defined.**

Lampiran 8 Hasil Uji *Turnitin*.....**Error! Bookmark not defined.**

Lampiran 9 Hasil Cek Abstrak.....**Error! Bookmark not defined.**

