

DAFTAR ISI

LEMBAR PERSETUJUAN	Error! Bookmark not defined.
LEMBAR PENGESAHAN	Error! Bookmark not defined.
LEMBAR PERNYATAAN	Error! Bookmark not defined.
KATA PENGANTAR.....	Error! Bookmark not defined.
ABSTRAK	Error! Bookmark not defined.
<i>ABSTRACT</i>	Error! Bookmark not defined.
DAFTAR TABEL	x
DAFTAR GAMBAR.....	xi
DAFTAR LAMPIRAN	xiii
BAB I PENDAHULUAN.....	Error! Bookmark not defined.
1.1. Latar Belakang	Error! Bookmark not defined.
1.2. Rumusan Masalah	Error! Bookmark not defined.
1.3. Tujuan Penelitian.....	Error! Bookmark not defined.
1.4. Manfaat.....	Error! Bookmark not defined.
BAB II TINJAUAN PUSTAKA.....	Error! Bookmark not defined.
2.1. PERUM PERURI.....	Error! Bookmark not defined.
2.2. <i>Fuzzy Logic</i> (Logika Fuzzy).....	Error! Bookmark not defined.
2.1.1. <i>Fuzzification</i>	Error! Bookmark not defined.
2.1.2. <i>Inference</i>	Error! Bookmark not defined.
2.1.3. <i>Defuzzification</i>	Error! Bookmark not defined.
2.3. Motor Induksi AC 1 Phase	Error! Bookmark not defined.
2.4. Arduino Uno.....	Error! Bookmark not defined.
2.5. Arduino IDE	Error! Bookmark not defined.
2.6. Kabel USB.....	Error! Bookmark not defined.
2.7. <i>Power Supply</i>	Error! Bookmark not defined.
2.8. PT100	Error! Bookmark not defined.
2.9. Modul MAX31865	Error! Bookmark not defined.
2.10. <i>Dimmer Module</i>	Error! Bookmark not defined.
2.11. LCD	Error! Bookmark not defined.
2.12. Tabel Penelitian Terkait	Error! Bookmark not defined.
BAB III METODE PENELITIAN	Error! Bookmark not defined.

3.1.	Objek Penelitian.	Error! Bookmark not defined.
3.2.	Prosedur Percobaan.	Error! Bookmark not defined.
3.2.1	Analisa Data.	Error! Bookmark not defined.
3.2.2	Perancangan.	Error! Bookmark not defined.
3.2.3	Implementasi.	Error! Bookmark not defined.
3.2.4	Pengujian.	Error! Bookmark not defined.
BAB IV HASIL DAN PEMBAHASAN		Error! Bookmark not defined.
4.1	Analisa Data.	Error! Bookmark not defined.
4.1.1.	Analisis Permasalahan.	Error! Bookmark not defined.
4.1.2.	Menentukan Akar Permasalahan.	Error! Bookmark not defined.
4.1.3.	Menguji Penyebab Akar Permasalahan.	Error! Bookmark not defined.
4.1.4.	Hasil Pengujian Akar Permasalahan.	Error! Bookmark not defined.
4.2	Perancangan.	Error! Bookmark not defined.
4.2.1.	<i>Flowchart</i> dan Pengembangan Sistem.	Error! Bookmark not defined.
	A. Setting Adafruit MAX31865 RTD Amplifier.	Error! Bookmark not defined.
	B. Menghubungkan LCD 20x4 Dengan IC I2C pada Arduino.	Error! Bookmark not defined.
	C. Setting AC Dimming Zero Crossing For Arduino UNO.	Error! Bookmark not defined.
4.2.2.	Sistem <i>Fuzzifikasi</i>	Error! Bookmark not defined.
	A. <i>Fuzzifikasi</i>	Error! Bookmark not defined.
	B. <i>Rule Base</i>	Error! Bookmark not defined.
	C. <i>Defuzzifikasi</i>	Error! Bookmark not defined.
4.2.3.	Implementasi.	Error! Bookmark not defined.
4.2.4.	Hasil Pengujian Sistem.	Error! Bookmark not defined.
	A. Pengujian Sensor Suhu PT100 dan Adafruit MAX31865.	Error! Bookmark not defined.
	B. Pengujian Penerapan Metode Fuzzy Pada Oil Cooler.	Error! Bookmark not defined.
	C. Evaluasi Implementasi	Error! Bookmark not defined.
BAB V KESIMPULAN DAN SARAN		Error! Bookmark not defined.
5.1.	Kesimpulan.	Error! Bookmark not defined.

5.2. Saran.....	Error! Bookmark not defined.
DAFTAR PUSTAKA	Error! Bookmark not defined.
LAMPIRAN.....	Error! Bookmark not defined.
DAFTAR RIWAYAT HIDUP	Error! Bookmark not defined.

DAFTAR TABEL

Tabel 1. 1 Data Frekuensi Gangguan Produksi.....	Error! Bookmark not defined.
Tabel 2. 1 Penelitian Terkait	Error! Bookmark not defined.
Tabel 3. 1 Rencana Penelitian.....	Error! Bookmark not defined.
Tabel 3. 2 Rumus Korelasi.....	Error! Bookmark not defined.
Tabel 3. 3 Hubungan Korelasi	Error! Bookmark not defined.
Tabel 4. 1 Analisa Kondisi Kejadian	Error! Bookmark not defined.
Tabel 4. 2 Tabel Percobaan I <i>Fuzzy VMS</i>	Error! Bookmark not defined.
Tabel 4. 3 Tabel Percobaan II <i>Fuzzy VMS</i>	Error! Bookmark not defined.
Tabel 4. 4 Implementasi	Error! Bookmark not defined.
Tabel 4. 5 Kebutuhan Sistem	Error! Bookmark not defined.
Tabel 4. 6 Pengujian Sensor Suhu PT100 dan Adafruit MAX31865.	Error! Bookmark not defined.
Bookmark not defined.	
Tabel 4. 7 Perbandingan Kondisi Oil Cooler	Error! Bookmark not defined.
Tabel 4. 8 Evaluasi Akar Permasalahan/Permasalahan <i>Oil Lubrication Machine</i>	Error! Bookmark not defined.
Tabel 4. 9 Evaluasi Kerusakan Permesinan	Error! Bookmark not defined.

DAFTAR GAMBAR

Gambar 1.1 Diagram Frekuensi Gangguan Produksi	Error! Bookmark not defined.
Gambar 1. 2 Diagram Downtime Gangguan Produksi.	Error! Bookmark not defined.
Gambar 2 1 PERUM PERURI (https://www.peruri.co.id).....	5
Gambar 2. 2 MRV 150 (kiri) MRH 150 (kanan). (https://www.machinetools.com/en/models/schuler-mrv-150).....	5
Gambar 2. 3 Diagram Flow Proses Oil Cooler.	6
Gambar 2. 4 Diagram Blok Sistem Berbasis Aturan Fuzzy.....	7
Gambar 2. 5 Motor Induksi 1 Phase. (https://www.airlinehyd.com/Product.aspx?item_code=HYDAC+2596451)	8
Gambar 2. 6 Arduino Uno.....	8
Gambar 2. 7 Work Page IDE.	9
Gambar 2. 8 USB Type A To USB Type B.....	10
Gambar 2. 9 Power Supply.....	10
Gambar 2. 10 Sensor PT100.	11
Gambar 2. 11 Modul MAX31865.....	11
Gambar 2. 12 Dimmer Zero Crossing Arduino.	11
Gambar 2. 13 LCD Module.	12
Gambar 3. 1 Prosedur Percobaan.	16
Gambar 3. 2 Diagram Ishikawa.	17
Gambar 3. 3 Rancangan Alat.	19
Gambar 3. 4 Skema.	19
Gambar 3. 5 Flowchart Sistem.....	20
Gambar 3. 6 Proses Fuzzifikasi Temperature.	21
Gambar 4. 1. Diagram Ishikawa Buruknya Lubrication System.	22
Gambar 4. 2. Diagram Loss Time.....	23
Gambar 4. 3. Diagram Frekuensi Kerusakan.	24
Gambar 4. 4 Prototype variabel motor pendingin pelumasan mesin.	25
Gambar 4. 5. Skema	25

Gambar 4. 6 Adafruit MAX31865 RTD.....	25
Gambar 4. 7 Setting PT100 3 kabel.	25
Gambar 4. 8 Sambungkan PT100 3 Kabel Dengan Modul MAX31865.	26
Gambar 4. 9 Konfigurasi Arduino Uno Dengan Adafruit MAX31865.	26
Gambar 4. 10 LCD 20x4 Atau LCD 2004 Dengan IC I2C.....	27
Gambar 4. 11 Konfigurasi Pin I2C Dan Arduino.	27
Gambar 4. 12 Konfigurasi Motor Oil Cooler Dengan Modul Dimmer.	28
Gambar 4. 13 Kurva Fuzzifikasi VMS	29
Gambar 4. 14 Rule Base VMS.....	30
Gambar 4. 15 Defuzzifikasi VMS.....	30



DAFTAR LAMPIRAN

Lampiran 1 Lembar Bimbingan Proposal Tugas Akhir.....	Error! Bookmark not defined.
Lampiran 2 Lembar Perbaikan Ketua Sidang Seminar Proposal TA	Error! Bookmark not defined.
Lampiran 3 Lembar Perbaikan Penguji Seminar Proposal Tugas Akhir	Error! Bookmark not defined.
Lampiran 4 Lembar Pengesahan Proposal Tugas Akhir.....	Error! Bookmark not defined.
Lampiran 5 Lembar Bimbingan Tugas Akhir.....	Error! Bookmark not defined.
Lampiran 6 Lembar Perbaikan Ketua Sidang	Error! Bookmark not defined.
Lampiran 7 Lembar Perbaikan Penguji I.....	Error! Bookmark not defined.
Lampiran 8 Lembar Perbaikan Penguji II.....	Error! Bookmark not defined.
Lampiran 9 Surat Keterangan Lulus Pengecekan Turnitin..	Error! Bookmark not defined.
Lampiran 10 Historis Mesin 2019	Error! Bookmark not defined.
Lampiran 11 <i>Historis</i> Mesin 2020	Error! Bookmark not defined.
Lampiran 12 Manual <i>Book Machine</i>	Error! Bookmark not defined.
Lampiran 13 Pengujian Sensor Suhu PT100 dan Adafruit MAX31865.....	Error! Bookmark not defined.
Lampiran 14 Kode Program Mencari Alamat I2C <i>Display</i>	53
Lampiran 15 Kode Program Percobaan I.....	55
Lampiran 16 Kode Program Percobaan II	60
Lampiran 17 Daftar Riwayat Hidup.....	6 Error! Bookmark not defined.

