

DAFTAR ISI

HALAMAN JUDUL	Error! Bookmark not defined.
LEMBAR PERSETUJUAN	Error! Bookmark not defined.i
LEMBAR PENGESAHAN	Error! Bookmark not defined.ii
LEMBAR PERNYATAAN	Error! Bookmark not defined.
KATA PENGANTAR.....	Error! Bookmark not defined.
ABSTRAK	Error! Bookmark not defined.
ABSTRACT	Error! Bookmark not defined.
DAFTAR ISI.....	ix
DAFTAR GAMBAR.....	xii
DAFTAR TABEL	xiii
DAFTAR RUMUS	xiv
DAFTAR LAMPIRAN	xv
BAB 1 PENDAHULUAN	Error! Bookmark not defined.
1.1. Latar Belakang Penelitian	Error! Bookmark not defined.
1.2. Perumusan Masalah.....	Error! Bookmark not defined.
1.3. Tujuan Penelitian.....	Error! Bookmark not defined.
1.4. Manfaat penelitian.....	Error! Bookmark not defined.
1.4.1. Manfaat Teoritis.....	Error! Bookmark not defined.
1.4.2. Manfaat Praktis	Error! Bookmark not defined.
1.5. Batasan Masalah.....	Error! Bookmark not defined.
BAB II TINJAUAN PUSTAKA.....	Error! Bookmark not defined.
2.1. Kajian Teori.....	Error! Bookmark not defined.
2.1.1. Pengertian Kualitas.....	Error! Bookmark not defined.
2.1.2. Pengertian Pengendalian Kualitas	Error! Bookmark not defined.
2.1.3. Produk Cacat	Error! Bookmark not defined.
2.1.4. Jenis-jenis Produk Cacat.....	Error! Bookmark not defined.
2.1.5. RCA	Error! Bookmark not defined.
2.1.6. <i>Failure Mode and Effect Analysis</i> (FMEA)	Error! Bookmark not defined.
2.2. Penelitian Terkait	Error! Bookmark not defined.

BAB III METODE PENELITIAN	Error! Bookmark not defined.
3.1. Objek Penelitian	Error! Bookmark not defined.
3.2. Prosedur Penelitian.....	Error! Bookmark not defined.
3.3. Desain Penelitian.....	Error! Bookmark not defined.
3.4. Jenis Data an Informasi	Error! Bookmark not defined.
3.5. Teknik Pengumpulan Data	Error! Bookmark not defined.
3.6. Populasi dan Sampel	Error! Bookmark not defined.
3.7. Teknik Analisis dan Pengolahan Data.....	Error! Bookmark not defined.
BAB IV HASIL DAN PEMBAHASAN	Error! Bookmark not defined.
4.1. Gambaran Umum Perusahaan	Error! Bookmark not defined.
4.2. Hasil Penelitian	Error! Bookmark not defined.
4.2.1 Pembuatan Histogram	Error! Bookmark not defined.
4.2.2 Membuat Peta Kendali p (p control)	Error! Bookmark not defined.
4.2.3 Membuat Diagram Sebab-Akibat.....	Error! Bookmark not defined.
4.3. Analisa Data <i>Root Cause Analysis</i> (RCA)	Error! Bookmark not defined.
4.4. <i>Failure Mode and Effect Analysis</i> (FMEA)	Error! Bookmark not defined.
4.4.1 <i>Severity</i>	Error! Bookmark not defined.
4.4.2 <i>Occurence</i>	Error! Bookmark not defined.
4.4.3 <i>Detection</i>	Error! Bookmark not defined.
4.4.4 Penilaian <i>Failure Mode and Effect Analysis</i> (FMEA) ...	Error! Bookmark not defined.
4.4.5 Menghitung <i>Risk Priority Number</i> (RPN) ..	Error! Bookmark not defined.
4.5. Rekomendasi Perbaikan	Error! Bookmark not defined.
4.5.1 Memodifikasi Saluran <i>Coolant</i> Menjadi <i>Inner</i>	Error! Bookmark not defined.
4.5.2 Membuat Program <i>Cutting</i> Baru untuk Velg Tipe SG1	Error! Bookmark not defined.
4.5.3 Memaksimalkan <i>Visual Check After Proses Machining</i>	Error! Bookmark not defined.
4.5.4 Menyamakan <i>Cycle Time Mesin Cutting</i> dengan <i>Cycle Time</i>	
<i>Hanger</i>	Error! Bookmark not defined.

4.6. <i>Failure Mode and Effect Analysis (FMEA) Konfirmasi</i>	Error! Bookmark not defined.
4.7. <i>Percobaan Implementasi Perbaikan</i>	Error! Bookmark not defined.
BAB V KESIMPULAN DAN SARAN	Error! Bookmark not defined.
5.1 Kesimpulan	Error! Bookmark not defined.
5.2 Saran	Error! Bookmark not defined.
DAFTAR PUSTAKA	Error! Bookmark not defined.
LAMPIRAN	Error! Bookmark not defined.
RIWAYAT PENULIS	Error! Bookmark not defined.



DAFTAR GAMBAR

Gambar 1.1 <i>Ratio Rework 2nd Machining</i>	2
Gambar 1.2 <i>Ratio Rework 2nd Machining Per Tipe</i>	2
Gambar 1.3 Data Produk Cacat Wheel Type SG1	4
Gambar 2.1 Lima langkah dasar dalam RCA	12
Gambar 3.1 <i>Flowchart</i> Penelitian	20
Gambar 4.1 PT. Central Motor <i>Wheel</i> Jakarta	25
Gambar 4.2 Tipe Produk <i>Wheel</i>	26
Gambar 4.3 Histogram Jenis Produk Cacat Bulan Agustus 2020-Januari 2021	29
Gambar 4.4 <i>Control Chart</i> Produk <i>Defect</i>	31
Gambar 4.5 Diagram Sebab-Akibat Produk Cacat (<i>Defect</i>) <i>Suji</i>	32
Gambar 4.6 Diagram Pareto Urutan Prioritas Kegagalan	42
Gambar 4.7 Jalur Pipa <i>Coolant</i>	43
Gambar 4.8 Modifikasi Jalur <i>Coolant</i>	43
Gambar 4.9 Contoh <i>Defect Suji</i> Karena <i>Kiriko</i>	44
Gambar 4.10 Contoh <i>Ishomenshu</i>	45
Gambar 4.11 Pengecekan Visual pada Proses <i>2nd Machining</i>	46
Gambar 4.12 Grafik Perbandingan Nilai RPN FMEA Awal dengan Nilai RPN FMEA Konfirmasi	50

DAFTAR TABEL

Tabel 1.1 Data Produk Cacat <i>Wheel Type</i> SG1.....	3
Tabel 2.1 Kriteria <i>Severity</i>	14
Tabel 2.2 Kriteria <i>Occurrence</i>	14
Tabel 2.3 Kriteria <i>Detection</i>	15
Tabel 2.4 Penelitian Terkait	16
Tabel 4.1 Jumlah Produk dan Jenis Cacat SG1 Bulan Agustus 2020 – Januari 2021	27
Tabel 4.2 Hasil Perhitungan Control Chart P	31
Tabel 4.3 RCA 5 <i>Why Method</i> Manusia	33
Tabel 4.4 RCA 5 <i>Why Method</i> Material.....	33
Tabel 4.5 RCA 5 <i>Why Method</i> Mesin.....	34
Tabel 4.6 RCA 5 <i>Why Method</i> Metode.....	34
Tabel 4.7 Hasil Klarifikasi Kegagalan dan Akar Penyebab Kegagalan dari RCA 35	
Tabel 4.8 <i>Severity</i>	36
Tabel 4.9 <i>Occurrence</i>	37
Tabel 4.10 <i>Detection</i>	38
Tabel 4.11 Hasil Penilaian FMEA	39
Tabel 4.12 Hasil Perhitungan RPN.....	41
Tabel 4.13 FMEA Konfirmasi	47
Tabel 4.14 <i>Risk Priority Number</i> (RPN) FMEA Konfirmasi	49

DAFTAR RUMUS

Rumus 2.1 <i>Risk Priority Number</i>	15
Rumus 3.1 Control Chart P	22
Rumus 3.2 Pusat Central Line.....	22
Rumus 3.3 Batas Kendali Atas.....	23
Rumus 3.4 Batas Kendali Bawah.....	23



DAFTAR LAMPIRAN

Lampiran 1 Tabel Rasio.....	57
Lampiran 2 Tabel Kumulatif.....	58
Lampiran 3 Contoh Check Sheet	59
Lampiran 4 Hasil Turnitin.....	60
Lampiran 5 Lembar Bimbingan.....	61

