


DAFTAR ISI

HALAMAN JUDUL.....	i
LEMBAR PERSETUJUAN	ii
LEMBAR PENGESAHAN.....	iii
LEMBAR PERNYATAAN.....	iv
KATA PENGANTAR	v
ABSTRAK.....	vii
ABSTRACT.....	viii
DAFTAR ISI.....	ix
DAFTAR GAMBAR.....	xi
DAFTAR TABEL.....	xii
DAFTAR RUMUS.....	xiii
DAFTAR LAMPIRAN	xiv
BAB I.....	15
1.1 Latar Belakang	15
1.2 Rumusan Masalah.....	17
1.3 Tujuan Penelitian	17
1.4 Batasan Masalah	17
1.5 Manfaat	18
BAB II TINJAUAN PUSTAKA.....	19
2.1 <i>Overall Equipment Effectiveness (OEE)</i>	19
2.1.1 <i>Availability Rate</i>	19
2.1.2 <i>Performance Rate</i>	20
2.1.3 <i>Quality Rate</i>	20
2.2 <i>Six Big Losses</i>	21
2.3 <i>Fishbone Diagram</i> (Diagram Sebab Akibat).....	22
2.4 <i>Proses Stamping</i>	23
2.5 Penelitian Terdahulu	24
2.6 Kerangka Pemikiran.....	30
BAB III METODE PENELITIAN.....	31
3.1 Waktu dan Tempat Penelitian.....	31
3.2 Objek Penelitian.....	31

3.2.1 Jenis Penelitian	31
3.3 Prosedur Penelitian	32
3.4 Pengumpulan Data	33
3.5 Teknik Pengumpulan Data	34
3.5.1 Data Yang Digunakan	35
3.6 Teknik Pengolahan Data	35
3.7 Analisis Data	37
3.8 Kesimpulan dan Saran	39
BAB IV HASIL DAN PEMBAHASAN	40
4.1 Hasil Pengumpulan Data	40
4.1.1 Profil Perusahaan	40
4.2.1 Data Produksi Mesin <i>Stamping</i> 3000 ton	41
4.2.2 Data <i>Production Time</i>	42
4.2.3 Data <i>Downtime</i> Mesin <i>Stamping</i> 3000 ton	42
4.3 Pengolahan Data	43
4.3.1 Perhitungan Nilai <i>Availability Rate</i>	43
4.3.2 Perhitungan <i>Performance Rate</i>	45
4.3.3 Perhitungan Nilai <i>Quality Rate</i>	48
4.3.4 Perhitungan nilai OEE	49
4.3.5 Perhitungan <i>Six Big Losses</i>	50
4.4 Analisis Data	55
4.4.1 Rekapitulasi Nilai <i>Overall Equipment Effectiveness</i> (OEE)	55
4.4.2 Rekapitulasi <i>Six Big Losses</i>	56
4.4.3 Analisis Fishbone Diagram (Cause and Effect)	57
4.4.4 Usulan Perbaikan	59
BAB V	61
KESIMPULAN DAN SARAN	61
5.1 Kesimpulan	61
5.2 Saran	62
DAFTAR PUSTAKA	63
LAMPIRAN	65
RIWAYAT PENULIS	75

DAFTAR GAMBAR

Gambar 1. 1 Grafik <i>downtime</i> pada Bulan Januari – Juni 2024	16
Gambar 2. 1 <i>Cause and Effect, Fishbone Diagram</i>	23
Gambar 2. 2 Kerangka pemikiran.....	30
Gambar 3. 1 Alur proses Penelitian	32
Gambar 4. 1 Mesin <i>stamping</i> 3000 ton.....	40
Gambar 4. 2 Grafik <i>availability rate</i>	45
Gambar 4. 3 Grafik <i>performance rate</i>	47
Gambar 4. 4 Grafik <i>quality rate</i>	49
Gambar 4. 5 Grafik persentase OEE.....	55
Gambar 4. 6 Grafik <i>six big losses</i> Mesin <i>Stamping</i> 3000 ton.....	57
Gambar 4. 7 <i>Fishbone diagram reduced speed losses</i> mesin <i>stamping</i> 3000 ton.....	58



DAFTAR TABEL

Tabel 2. 1 Penelitian Terdahulu	24
Tabel 4. 1 Data Produksi Januari-Juni 2024	41
Tabel 4. 2 Data Waktu Produksi Januari – Juni 2024.....	42
Tabel 4. 3 Data <i>downtime</i> mesin Stamping 3000 ton	43
Tabel 4. 4 Data <i>operation time</i> bulan Januari – Juni 2024	44
Tabel 4. 5 Perhitungan persentase <i>availability rate</i>	44
Tabel 4. 6 Data perhitungan nilai GSPH	46
Tabel 4. 7 Perhitungan nilai SPH.....	46
Tabel 4. 8 Perhitungan nilai <i>performance rate</i>	47
Tabel 4. 9 Perhitungan <i>quality rate</i>	48
Tabel 4. 10 Perhitungan nilai OEE	50
Tabel 4. 11 Perhitungan <i>breakdown losses</i>	50
Tabel 4. 12 Perhitungan <i>setup and adjustment losses</i>	51
Tabel 4. 13 Perhitungan nilai <i>idle and minor stoppages</i>	52
Tabel 4. 14 Perhitungan <i>reduced speed losses</i>	53
Tabel 4. 15 Perhitungan <i>Defect losses</i>	54
Tabel 4. 16 Perhitungan nilai <i>reduced yield</i>	54
Tabel 4. 17 Rekapitulasi hasil perhitungan <i>six big losses</i>	56

DAFTAR RUMUS

2. 1 Rumus OEE.....	19
2. 2 Rumus <i>Loading Time</i>	20
2. 3 Rumus <i>Operation Time</i>	20
2. 4 Rumus <i>Availability Rate</i>	20
2. 5 Rumus <i>Performance Rate</i>	20
2. 6 Rumus <i>Quality Rate</i>	21
2. 7 Rumus <i>Breakdown Losses</i>	21
2. 8 Rumus <i>Setup and Adjustment Losses</i>	21
2. 9 Rumus <i>Idle and Minor Stoppages Losses</i>	22
2. 10 Rumus <i>Reduce Speed Losses</i>	22
2. 11 Rumus <i>Defect Losses</i>	22
2. 12 Rumus <i>Reduce Yield</i>	22
3. 1 Rumus <i>Availability Rate</i>	36
3. 2 Rumus <i>Performance Rate</i>	36
3. 3 Rumus <i>Quality Rate</i>	36
3. 4 Rumus OEE.....	37
4. 1 Rumus <i>Operation Time</i>	43
4. 2 Rumus <i>Availaibilty Rate</i>	44
4. 3 Rumus GSPH... ..	45
4. 4 Rumus SPH... ..	46
4. 5 Rumus <i>Performance Rate</i>	46
4. 6 Rumus <i>Quality Rate</i>	48
4. 7 Rumus OEE.....	49
4. 8 Rumus <i>Breakdown Losses</i>	50
4. 9 Rumus <i>Setup and Adjustment Losses</i>	51
4. 10 Rumus <i>Idle and Minor Stoppages Losses</i>	52
4. 11 Rumus <i>Reduced Speed Losses</i>	53
4. 12 Rumus <i>Defect Losses</i>	53
4. 13 Rumus <i>Reduced Yield</i>	54