

DAFTAR ISI

LEMBAR PERSETUJUAN	Error! Bookmark not defined.
LEMBAR PENGESAHAN	Error! Bookmark not defined.
LEMBAR PERNYATAAN	Error! Bookmark not defined.
KATA PENGANTAR.....	Error! Bookmark not defined.
DAFTAR ISI.....	vii
DAFTAR GAMBAR.....	viii
DAFTAR TABEL	ix
DAFTAR LAMPIRAN.....	x
PENDAHULUAN.....	Error! Bookmark not defined.
LANDASAN TEORI.....	Error! Bookmark not defined.
METODOLOGI.....	Error! Bookmark not defined.
HASIL DAN PEMBAHASAN.....	Error! Bookmark not defined.
KESIMPULAN.....	Error! Bookmark not defined.
UCAPAN TERIMA KASIH.....	Error! Bookmark not defined.
DAFTAR PUSTAKA	Error! Bookmark not defined.
LAMPIRAN.....	Error! Bookmark not defined.
RIWAYAT PENULIS.....	Error! Bookmark not defined.

KARAWANG

DAFTAR GAMBAR

- Gambar 1.** Flowchart Alur Penelitian.....**Error! Bookmark not defined.**
Gambar 2. Data Kerusakan Mesin Produksi PT. Sub Otomotif, 2024 **Error! Bookmark not defined.**
Gambar 3. Diagram Kerusakan Mesin Welding CO₂ 2024**Error! Bookmark not defined.**
Gambar 4. Grafik Nilai Risk Priority Number**Error! Bookmark not defined.**



DAFTAR TABEL

Tabel 1. Frekuensi Kerusakan Mesin Welding CO₂ Selama 6 Bulan Ditahun 2024 **Error! Bookmark not defined.**

Tabel 2. Data Ringkas Kerusakan Komponen Mesin Welding CO₂ Selama 6 Bulan Ditahun 2024.....**Error! Bookmark not defined.**

Tabel 3. Data Analisis Keandalan Mesin Welding CO₂ Selama 6 Bulan..... **Error! Bookmark not defined.**

Tabel 4. Hasil Analisis Nilai Risk Priority Number (RPN) **Error! Bookmark not defined.**

Tabel 5. Job Activity Penjadwalan Preventive Maintenance Mesin Welding CO₂ .. **Error! Bookmark not defined.**



DAFTAR LAMPIRAN

- Lampiran 1.** Loa Jurnal Penelitian**Error! Bookmark not defined.**
Lampiran 2. Produk Dump Truck**Error! Bookmark not defined.**
Lampiran 3. Dokumentasi Bersama Kepala Maintenance **Error! Bookmark not defined.**

